

30

319

24/11/15

“स्वच्छ भारत अभियान”

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: LEHANGA

SCHOOL NAME: LEHANGA PS

SCHOOL CODE: 21170404501

NO. OF STUDENT: 49

GIRLS: 24

BOYS: 25

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2	—
2	URINALS	— X	—
3	DOORS(SIZE)	✓	✓
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: * New urinals need to be constructed
 * Overhead tank with water supply required
 * No electricity supply inside premises.

P.K. Behera

Sign of School Head Master
HEADMASTER

Lehanga Primary School

NAME: Balraj Kumar Behera

Chhabirani School

Sign of School Mgt Committee

CHAIRPERSON, S.M.C.
Lehanga Primary School

NAME: Chhabirani Sahu

[Signature]

Sign of Surveyor

[Signature]
24/11/15

NAME: Pankaj Kumar

Asstt. IC Patilwal