

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: MUKTAPUR

SCHOOL NAME: MUKTAPUR PS

SCHOOL CODE: 21170467501

NO. OF STUDENT: 68

GIRLS: 27

BOYS: 41

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

| SI.NO. | ITEM | CONDITION | |
|--------|------------------------|--------------|------------------------|
| | | GOOD IN NOS. | TO BE REPLACED IN NOS. |
| 1 | WC | / | / |
| 2 | URINALS | | |
| 3 | DOORS(SIZE) | | |
| 4 | FLOOR LEVEL | | |
| 5 | WALL LEVEL | | |
| 6 | INTERNAL PLASTER | | |
| 7 | OUTER PLASTER | | |
| 8 | INSPECTION CHAMBER | | |
| 9 | LEASE PIT/ SEPTIC TANK | | |

SOURCE OF WATER: WELL

BORE WELL WITH PUMP: ✗

HAND PUMP: ✓

WATER TANK:

GROUND: ✗

OVERHEAD: ✗

WATER TANK CAPACITY:

Remarks if any:

* Existing toilet fully damaged.
 * New toilets and urinals with all facilities required.

Sign of School Head Master

Maha Keshri Bealon
 NAME:

Sasmita Sahoo
 Sign of School Mgt Committee

NAME:

Sign of Surveyor

Anu Kumar Jaiswal
 28/1/15

NAME: