



328

28/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: NIAMUNHAN

SCHOOL NAME: NIAMUNHA PPS

SCHOOL CODE: 21170410401

NO. OF STUDENT: 20

GIRLS: 8

BOYS: 12

STATUS OF TOILET:

EXISTING:

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	✓
2	URINALS	2 No.	Need to be repaired
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	1	Damaged

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓ (Damaged)

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any:

* Existing toilet damaged
* New construction required

Sign of School Head Master

NAME:

Chhabi Rani' School
Sign of School Mgt Committee
Chairperson SMC

Niamuhan Project Pa
NAME: Niamuhan Khe

Sign of Surveyor

NAME: P. K. Das
Ann. K. Das