

"स्वच्छ भारत अभियान"

DISTRICT: KHURDA BLOCK: BEAUNIA VILLAGE: NIDHIPUR
SCHOOL NAME: NIDHIPUR U.G.M.E.S SCHOOL CODE: 21170407701
NO. OF STUDENT: 180 GIRLS: 92 BOYS: 88
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: X
TOILET REQUIREMENT: GIRLS: 1 BOYS: 2
IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: *village water supply* BORE WELL WITH PUMP: X HAND PUMP: ✓
WATER TANK: GROUND: ✓ OVERHEAD: X
WATER TANK CAPACITY: 750 lit.

Remarks If any: * Existing toilet fully damaged
 * New construction with full facilities required
 * Toilet exists for girls but no urinal separately

[Signature]
 Sign of School Head Master
Headmaster
Nidhipur U.G.M.E. School
 NAME: *Beren Kumar Pattnayak*
 Hea:
 Nidhipur U.G.M.E. School

[Signature]
 Sign of School Mgt Committee
Chairperson SMC
Nidhipur U.G.M.E School
 NAME: *Balabantary*
 Nidhipur, Dist-Khordha

[Signature]
 Sign of Surveyor
NAME: *Arun Kumar Pattnayak*
 28/1/15
[Signature]