

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: NILAKANTHAPUR

SCHOOL NAME: NILAKANTHAPUR PS

SCHOOL CODE: 21170411901

NO. OF STUDENT: 64

GIRLS: 31

BOYS: 33

STATUS OF TOILET:

EXISTING:

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 No.	Damaged - To be replaced
2	URINALS	X	—
3	DOORS(SIZE)	X	—
4	FLOOR LEVEL	X	—
5	WALL LEVEL	X	—
6	INTERNAL PLASTER	X	—
7	OUTER PLASTER	X	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	X	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: But damaged

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: * New Toilet infrastructure to be constructed including overhead tank, power supply etc
* No power supply inside the premises.

Annapurna Mahapatra

23.01.2015
Sign of School Head Master

Sign of School Mgt Committee

Headmaster
Nilakanthapur Project Primary School

NAME:

NAME:

Sign of Surveyor

NAME:

23/1/15
P. K. Panda
Anur K. Patil'swal