

"स्वच्छ भारत अभियान"

DISTRICT: KHURDA

BLOCK: BEAUNNA

VILLAGE: OGALPUR

SCHOOL NAME: OGALPUR P UPS

SCHOOL CODE: 21170403901

NO. OF STUDENT: 60

GIRLS: 28

BOYS: 32

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: ✗

HAND PUMP: ✓

WATER TANK:

GROUND: ✗

OVERHEAD: ✗

WATER TANK CAPACITY:

Remarks if any:

✗ Existing toilet fully damaged
 ✗ New construction with all facilities required. *Alor*

Ajayade

Sign of School Head Master
 HEADMASTER
 Ogalpur Project Upper Primary School,
 Ogalpur, Khurda

NAME: *Ashok Kumar Nayak**Nayak*

Sign of School Mgt Committee

No committee

NAME:

Amr
28/1/15

Sign of Surveyor

Arun Kumar Jaiswal

NAME: *Arun Kumar Jaiswal*