

"स्वच्छ भारत अभियान"

DISTRICT: KHURDA

BLOCK: BEGUNIA

VILLAGE: BEGUNIA

SCHOOL NAME: PANCHAYAT SAMITI PS

SCHOOL CODE: 0401305

NO. OF STUDENT: 76

GIRLS: 43

BOYS: 33

STATUS OF TOILET:

EXISTING: 01 BLOCK

NOT EXISTING: -

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 NO.	1 to be constructed
2	URINALS	2 NO's	<del>1</del> -
3	DOORS(SIZE)	2 NO's	2'x6' 1 Door to be replaced
4	FLOOR LEVEL	✓	-
5	WALL LEVEL	✓	-
6	INTERNAL PLASTER	✓	-
7	OUTER PLASTER	✓	-
8	INSPECTION CHAMBER	X	To be constructed
9	LEASE PIT/ SEPTIC TANK X	-	to be newly constructed

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓ inside school premises

WATER TANK: No water tank nearby toilet -

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY: Approx. 500 ltr. in school premises

Remarks If any: \* Water carried by bucket from school water tank to the toilet.

\* PH water supply  
\* This is co-education school

22.01.15

Sign of School Head Master  
Panchayat Samiti Primary School  
Begunia.

NAME: Saileshata Saha

Sign of School Mgt Committee

Tapay Kumar Behera  
CHAIRMAN

NAME: Tapay Kumar Behera  
Panchayat Samiti Primary School  
BEGUNIA

Sign of Surveyor

NAME: Anam K. Jaiswal

Tapay Kumar Behera