



333

23/1/15

“स्वच्छ भारत अभियान”

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: PANGARSINGH

SCHOOL NAME: PANGARSINGH UGUPS

SCHOOL CODE: 21170411302

NO. OF STUDENT: 86

GIRLS: 26

BOYS: 50

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: X

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: * Required new toilets and urinals with all facilities such as water supply etc.
* Existing toilet fully damaged

Nakula Chandra Singh
Sign of School Head Master
23/1/2015
PANGARSINGH U.G.M.E SCHOOL

Sign of School Mgt Committee

Sign of Surveyor

NAME: PANI

NAME: X

NAME: P. U. Poul

HEADMASTER
PANGARSINGH U.G.M.E SCHOOL
PANGARSINGH KHURDA

Arum K. Jaiswal