

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA      BLOCK: BEUNIA      VILLAGE: PARICHHALA  
 SCHOOL NAME: PARICHHAL ADIVASI SAHI PS      SCHOOL CODE: 21170404002  
 NO. OF STUDENT: 33      GIRLS: 12      BOYS: 21  
 STATUS OF TOILET:      EXISTING:       NOT EXISTING:   
 TOILET REQUIREMENT:      GIRLS: 1      BOYS: 1  
 IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:      BORE WELL WITH PUMP:       HAND PUMP:   
 WATER TANK:      GROUND:       OVERHEAD:   
 WATER TANK CAPACITY:

Remarks If any: *\* Existing toilet fully damaged. New urinals and toilets need to be constructed with full facilities.*

*C. Pradhan Sahoo*  
 Sign of School Head Master

*जयश्री साहू*  
 Sign of School Mgt Committee

*Jeel*  
 Sign of Surveyor  
*Pran*  
 NAME: *K. C. Prasad*  
*Asstt. IC, Palswal*  
 25/1/15

NAME: *...*

NAME: *...*