

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: SIKO

SCHOOL NAME: PINDAMULA PS

SCHOOL CODE: 21170416102

NO. OF STUDENT: 45

GIRLS: 20

BOYS: 25

STATUS OF TOILET:

EXISTING:

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 No.	Need to be built
2	URINALS	—	
3	DOORS(SIZE)	—	Need to be replaced 6'x2.5'
4	FLOOR LEVEL	—	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	X	Plastering required
7	OUTER PLASTER	X	—
8	INSPECTION CHAMBER	X	
9	LEASE PIT/ SEPTIC TANK	✓	Damaged

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP:

WATER TANK:

GROUND:

OVERHEAD:

WATER TANK CAPACITY:

Remarks If any: *

- Overhead tank with water supply required
- Roofing required for urinal and toilet.
- Needs full renovation

Peey
 Sign of School Head Master
 Pindamul Pry. School
 P.O Siko, Dist-Khordha
 NAME:

ଶ୍ରୀମତୀ ଗଜେନ୍ଦ୍ରୀ
 Sign of School Mgt Committee
 Chairman, S.M.C
 Pindamul Pry. School
 P.O Siko, Dist-Khordha
 NAME:

Amr
 Sign of Surveyor
 Amr Kumar Pansal
 NAME: P. U. Pansal
 26/1/15

Jogeshwar Choudhary