

276

28/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: BELAPADA

SCHOOL NAME: PURNAMASI PATANA RPS

SCHOOL CODE: 21170417101

NO. OF STUDENT: 47

GIRLS: 25

BOYS: 22

STATUS OF TOILET:

EXISTING: X

NOT EXISTING: X

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: X

BORE WELL WITH PUMP: X

HAND PUMP: X

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: School exists in club room. No school building exists. as per statement of head mistress. Full building construction required.

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

NAME:

NAME:

NAME:

Suniti bala Prichandan

Satish Kumar Mishra

28/1/15
Arun Kumar Daiswal