

324

28/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNIA

VILLAGE: MANTRI

SCHOOL NAME: RAMCHANDRAPUR PS

SCHOOL CODE: 21170406404

NO. OF STUDENT: 35

GIRLS: 16

BOYS: 19

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: X

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 in No.	—
2	URINALS	2 in No.	—
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooring Required
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Needs to be repaired

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any:
 * Overhead tank with water supply required to toilets
 * Flooring required.

R. S. S. T. O.

Sign of School Head Master
 Headmaster
 Ramachandrapur Pry. School

NAME: Ratnakar S. T. O.

Sign of School Mgt Committee
 Chairman S.M.C
 Ramachandrapur Pry. School

NAME:

Sabita Pattanayak

Chairman S.M.C
 Ramachandrapur Pry. School

Sign of Surveyor
 28/1/15
 Anon Kumar Patra

NAME:

Anon Kumar Patra