

34 342

24/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNNA VILLAGE: SAHADAPUT
 SCHOOL NAME: SAHADAPUT PROJECT PS SCHOOL CODE: 21170416701
 NO. OF STUDENT: 32 GIRLS: 11 BOYS: 21
 STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: —
 TOILET REQUIREMENT: GIRLS: 1 BOYS: X
 IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	—
2	URINALS	2	1 to be repaired
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	Needs to be increased
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓ 1	Damaged

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: ✓
 WATER TANK: GROUND: X OVERHEAD: X
 WATER TANK CAPACITY:

Remarks If any: * Flooding needs to be done in toilet
 * Overhead tank with water supply to the toilet required
 * Roofing required.

Sahoo
 Sign of School Head Master

Sign of School Mgt Committee
 Chairman
 Absent

Sahoo
 Sign of Surveyor

NAME: Jogesh chandra Sahoo

NAME: member

NAME: Anur K. Dasgupta
 24/1/15

Headmaster
 Sanadaput Project Prg. School

Manjuleeta Sahoo