

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: SANA TULASIPUR

SCHOOL NAME: SANATULSIPUR PS

SCHOOL CODE: 21170412401

NO. OF STUDENT: 92

GIRLS: 40

BOYS: 52

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: X

TOILET REQUIREMENT:

GIRLS: 1

BOYS: X

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 No	—
2	URINALS	2 No's	—
3	DOORS(SIZE)	X	3 doors of 6' x 2.5' need to be replaced
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	To be repaired

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: ✓

OVERHEAD: X

WATER TANK CAPACITY: 1000 Ltr. approx.

Remarks if any: * village water supply to tank
* water supply to the toilets required
* doors need to be changed

Ranjita Pradhan
Sign of School Head Master

D. 23.01.2015

NAME:

9861087734

ଶ୍ରୀମତୀ ପରୀଦା
Sign of School Mgt Committee

୨୩ = ୧ = ୧୧

NAME:

Basanti Parida

(Committee member)
Cem
Councillor

Suraj
Sign of Surveyor

23/1/15
NAME: P. K. Parida

A. K. Pariswal