

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: SIKO

SCHOOL NAME: SIKO CPS

SCHOOL CODE: 2117 0416103

NO. OF STUDENT: 132

GIRLS: 66

BOYS: 66

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 2

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	—
2	URINALS	—	—
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooding Required
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Damaged

SOURCE OF WATER: Village Water supply

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: ✓

OVERHEAD: X

WATER TANK CAPACITY: 1000 Ltr

Remarks If any: \* Overhead tank with water supply required  
\* No electricity  
\* Urinals need to be renovated. Toilets require flooring

*Subasena Soren*

Sign of School Head Master  
HEADMASTER  
Siko Primary School

NAME: Subasena Soren

Sign of School Mat Committee  
Siko Centre Pny. School  
Po-Siko, Dist-Khordha

NAME:

Sign of Surveyor  
Arum Kumar Prasad  
NAME: Arum Kumar Prasad