



350

24/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNIA VILLAGE: THANAPALLI
 SCHOOL NAME: THANAPALLI PS SCHOOL CODE: 21170414101
 NO. OF STUDENT: 26 GIRLS: 13 BOYS: 13
 STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: ←
 TOILET REQUIREMENT: GIRLS: 1 BOYS: X
 IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	1 No. to be replaced
2	URINALS	2 w' NO.	To be repaired
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	Wall level to be increased
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Damaged, Needs to be repaired

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: ✓
 WATER TANK: GROUND: X OVERHEAD: X
 WATER TANK CAPACITY:

Remarks If any: * Existing toilet damaged. Needs to be repaired.
 * Overhead tank with water supply required

Sign of School Head Master
 HEADMASTER
 Thanapalli Primary School

Sign of School Mgt Committee
 Absent
 NAME: Khetrabasi Mahto
 NAME: committee member
 ↓
 [Signature]

Sign of Surveyor
 [Signature]
 24/11/15
 NAME: P.K. Patra
 Arun K. Patra