

153

(21)  
295

District Bolangir Block Belpenda. Village Chandrapur  
 School Name Chandrapur Govt. PS. School Code 21240411301  
 No. of Student 68 Girls- 32 Boys- 36  
 Status of toilet Existing  Not Existing  
 Toilet Requirement Girls Boys One

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	-	1 (damaged)
2	Urinals		2 (damaged)
3	Doors (size)		3 (damaged).
4	Floor level		Damaged.
5	Wall level		do
6	Internal plaster		do.
7	Outer plaster		do.
8	Inspection Chamber	Nil.	
9	Lease pit / septic tank		damaged.

Source of Water  Bore well with pump /  Hand pump One  
 Water tank Nil. Ground / Overhead  
 Water tank Capacity

Remarks if any: During dry seasons no water come out from hand pump.

Sign of School head master Nirabati Saban Head Master Chandrapur P.S.  
 Name Nirabati Saban Mob No. 8018773067  
 Sign of School Mgt Committee for Chandrapur Pry. School  
 Name Chandrapur Bisi Bhagyawati Bisi  
 Sign of Surveyor Nabaram Das Asst-Manager (M) MT(CD) DA  
Praveen Sani