

5

5

175

District Bolenger Block Belpada Village Dheungiamunde  
 School Name Dheungiamunde Govt NVPS School Code 21240401 801  
 No. of Student 119 Girls- 60 Boys- 59  
 Status of toilet Existing 1 (SSA), 1 damaged Not Existing  
 Toilet Requirement Girls Not Boys 1

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1
2	Urinals		1
3	Doors (size)		3
4	Floor level		To be Repair
5	Wall level		To be Repair
6	Internal plaster		To be Repair
7	Outer plaster		To be Repair
8	Inspection Chamber	Not	
9	Lease pit / septic tank		To be Repair

Source of Water Bore well with pump / Hand pump  (drain required)  
 Water tank 1 (not working) / Overhead  
 Water tank Capacity 1000 ltr

Remarks if any: One damaged toilet exist  
one girl toilet by SSA.

[Signature]  
 Head Master  
 Sign of School head master  
Dheungiamunde  
Sugrekh Mathi  
 Name

[Signature]  
 Sign of School Mgt Committee  
 Govt. Project U.P.S  
Dheungiamunde  
Younanga Bag  
 Name

[Signature]  
 Sign of Surveyor  
A.M.(M)  
Santosh Kumar Mishra  
Ramakant Patel  
 Name

9938312924

1000  
[Signature]

4/05/2015  
M.T.(C)