

155

(23)  
297

District Bolangir Block Belpada. Village Jharimunda.  
 School Name Jharimunda govt. P.S. School Code 21240411501  
 No. of Student 15 Girls- 08. Boys- 07  
 Status of toilet Existing One . Not Existing  
 Toilet Requirement Girls One . Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		<u>One (danged)</u>
2	Urinals		<u>2 (two).</u>
3	Doors (size)		<u>3 (danged).</u>
4	Floor level		<u>danged.</u>
5	Wall level	<u>Ok.</u>	<u>0</u>
6	Internal plaster	<u>Ok.</u>	
7	Outer plaster	<u>Ok.</u>	
8	Inspection Chamber	<u>NIL.</u>	
9	Lease pit / septic tank		<u>Danged.</u>

Source of Water  Bore well with pump /  Hand pump One .  
 Water tank NIL Ground / Overhead  
 Water tank Capacity

Remarks if any:

Bansidhar Mallik  
 Sign of School Head master  
 Name Bansidhar Mallik.

Trinath Neel  
 Sign of School Mtg Committee  
 Name Trinath Neel.

Praveen Sai  
 Sign of Surveyor  
 Asst. Manager (M)  
 Name Praveen Sai  
Nabarun Das  
 MT(CD), DA

Phno- 9338579660.  
(H.M)

Praveen Sai