

DT. 24.01.15


"स्वच्छ भारत अभियान"


DISTRICT: NAYAGARH BLOCK: Bahapur VILLAGE: Anandapur
 SCHOOL NAME: Anandapur PPS SCHOOL CODE: 0105701
 NO. OF STUDENT: 30 GIRLS: 20 BOYS: 10
 STATUS OF TOILET: EXISTING: YES NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: Yes BOYS: Yes
 IF EXISTING:


SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X	2 nos required new
2	URINALS	X	2 nos both girls & boys.
3	DOORS(SIZE)	X	4 nos
4	FLOOR LEVEL	X	Re-construct
5	WALL LEVEL	✓	Repair required
6	INTERNAL PLASTER	✓	— do —
7	OUTER PLASTER	✓	— do —
8	INSPECTION CHAMBER	X	New construction required
9	LEASE PIT/ SEPTIC TANK	X	— do —

SOURCE OF WATER: NIL BORE WELL WITH PUMP: NIL HAND PUMP: YES
 WATER TANK: GROUND: NIL OVERHEAD: NIL

WATER TANK CAPACITY: 1. No water source hand pump is drop.
 2. Toilet dont have water supply or source.
 Remarks If any: water requirement & availability after 1 1/2 km.


 Sign of School Head Master
 Headmaster
 Anandapur Project Pry. School
 NAME: Bhanur, Dist-Nayagarh
 Dayanidhi Subudhi


 Sign of School Mgt Committee
 S.M.C. Chairman
 Anandapur Project Pry. School
 NAME: Bhapur, Nayagarh
 P.K. Mishra


 Sign of Surveyor
 NAME: S.S. Pattanayak
 Vasu
 Varun Kumar