

Date - 22.01.15.

(9)

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: BHAPUR

VILLAGE: BADABARA

SCHOOL NAME: BADABARA PS

SCHOOL CODE: 0108301

NO. OF STUDENT: 31

GIRLS: 19

BOYS: 12

STATUS OF TOILET:

EXISTING: YES

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: NIL

BOYS: NIL

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2	
2	URINALS	1	Required for boys
3	DOORS(SIZE)	2	1 Damage
4	FLOOR LEVEL	✓	
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER	✓	
9	LEASE PIT/ SEPTIC TANK	✓	

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP: 1.

WATER TANK:

GROUND: NIL

OVERHEAD: NIL

WATER TANK CAPACITY:

Remarks if any: 1. Urinal for boys to be constructed
2. Hand pump installed before is not functioning
3. Another arrangement required for water source

Sign of School Head Master

Jaganath Behera
Headmaster
Badabara Primary School
Bhapur Nayagarh

Sign of School Mgt Committee

Kalyani Swain
NAME: Kalyani Swain
Chairperson (S.M.C.)
Badabara Primary School
Bhapur, Nayagarh

Sign of Surveyor

Varun
NAME: Varun Kumar

S.S. Pattnayak