

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: Bhapur
SCHOOL NAME: Thagarpada PS
NO. OF STUDENT: 108 GIRLS: 55
STATUS OF TOILET: EXISTING: YES
TOILET REQUIREMENT: GIRLS: Y/NH
IF EXISTING:

VILLAGE: Thagarpada
SCHOOL CODE: 0109301
BOYS: 53
NOT EXISTING:
BOYS: YES

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X	2 nos Leach boy & Girls
2	URINALS	X	Reconstruct
3	DOORS(SIZE)	X	To be replaced
4	FLOOR LEVEL	X	replace
5	WALL LEVEL	X	re construct
6	INTERNAL PLASTER	X	re construct
7	OUTER PLASTER	yes	Maintenance
8	INSPECTION CHAMBER	yes	Not exist
9	LEASE PIT/ SEPTIC TANK	yes	not under working condition

SOURCE OF WATER: BORE WELL WITH PUMP: Phd. HAND PUMP:
WATER TANK: GROUND: Yes. OVERHEAD:
WATER TANK CAPACITY: Approx 500lt-

Remarks if any: 1. Boys urinal & toilet to be reconstitute
 2. Girls urinal & toilet maintenance to be done.
 3. Overhead tank required with appropriate supply need

M. Mallik
 Sign of School Head Master
 Thagarpada Primary School

Chairperson SMC
 Thagarpada Panch Committee
 Block-Bhapur Nayagarh

Sign of Surveyor
 Vam

NAME: Mayadhar Mallik

NAME: Bhagi Pradhan NAME: Vam Kumar

S. S. Pattanayak
 S.S. Pattanayak