

Dt: 24.01.15 (4)

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: Bharpur Khandapada VILLAGE: Nuagaon
 SCHOOL NAME: Nuagaon KBN High School SCHOOL CODE: 0110801
 NO. OF STUDENT: 200 GIRLS: 76 BOYS: 124
 STATUS OF TOILET: EXISTING: YES NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: YES BOYS: YES
 If EXISTING:

| SI.NO. | ITEM | CONDITION | |
|--------|------------------------|--------------|----------------------------|
| | | GOOD IN NOS. | TO BE REPLACED IN NOS. |
| 1 | WC | X | 2 nos both boys & girls |
| 2 | URINALS | X | 2 nos both boys & girls |
| 3 | DOORS(SIZE) | X | 3x6' - 4 nos. |
| 4 | FLOOR LEVEL | ✓ | Need repair |
| 5 | WALL LEVEL | ✓ | do |
| 6 | INTERNAL PLASTER | ✓ | do |
| 7 | OUTER PLASTER | ✓ | do |
| 8 | INSPECTION CHAMBER | X | New construction required |
| 9 | LEASE PIT/ SEPTIC TANK | ✓ | Need repair or reconstruct |

PHD connection

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: YES
 WATER TANK: GROUND: OVERHEAD: YES

WATER TANK CAPACITY: 700dt

Remarks If any: 1. Existing structure of urinal & toilet is in very bad shape.
 2. Overhead to be connected to toilet as water requirement for toilet is carried by bucket.

24.1.15
 Sign of School Head Master
HEADMASTER
 Kabiraj Baidyanath High School
 Nuagaon, Bharpur, Nayagarh

Tapaswini School
 Sign of School Mgt Committee
CHAIRMAN, S.M.C
 Kabiraj Baidyanath High School
 NAME: Nuagaon

S. S. Pattanayak
 Sign of Surveyor

For fulla Kuman Dash

TAPASWINI SAHOO.

NAME: S. S. Pattanayak
Vasun
 Vasun Kumar