

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: Bhopur

VILLAGE: Patharachakada

SCHOOL NAME: Patharachakada P.U.P.S.

SCHOOL CODE: 0109801

NO. OF STUDENT: 185 GIRLS: 90

BOYS: 95

STATUS OF TOILET: EXISTING: YES

NOT EXISTING:

TOILET REQUIREMENT: GIRLS: NO

BOYS: YES

If EXISTING:

| SI.NO. | ITEM                   | CONDITION    |                                  |
|--------|------------------------|--------------|----------------------------------|
|        |                        | GOOD IN NOS. | TO BE REPLACED IN NOS.           |
| 1      | WC                     | X            | Required new for both boy & girl |
| 2      | URINALS                | 1            | Required new for boys            |
| 3      | DOORS(SIZE)            | 3            |                                  |
| 4      | FLOOR LEVEL            | X            |                                  |
| 5      | WALL LEVEL             | 1            |                                  |
| 6      | INTERNAL PLASTER       | ✓            | Boys Urinal & Toilet Requir      |
| 7      | OUTER PLASTER          | ✓            | Required in Boys Urinal & Toilet |
| 8      | INSPECTION CHAMBER     | X            | To be constructed                |
| 9      | LEASE PIT/ SEPTIC TANK | 1            | Required Repair for Boys & girls |

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP: YES

WATER TANK:

GROUND: NIL

OVERHEAD: NIL

WATER TANK CAPACITY:

Remarks If any:

1. Boy Urinal & toilet to be repaired
2. Girls Urinal & toilet needs maintenance
3. Tube well not functioning
4. No ground tank or overhead tank to store water, all requirement filled by Govt. arrangement

22.01.15  
 Sign of School Head Master  
 Patharachakada P.U.P.School

Bhramorbar Rout  
 Sign of School Mgt Committee  
 Chairman (S.M.C.)  
 Patharachakada P.U.P.S.

Sign of Surveyor  
 Vasun

NAME: Dasarathi Rayan

NAME: Bhramorbar Rout

NAME: Vasun Kumar

S.S. Pathangyal