

Date - 22.01.15 (7)

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH **BLOCK:** Bhapur **VILLAGE:** Upper Bausabati
SCHOOL NAME: UPPER BAUSABATI PPS **SCHOOL CODE:** 0103501
NO. OF STUDENT: 28 **GIRLS:** 11 **BOYS:** 17
STATUS OF TOILET: **EXISTING:** YES **NOT EXISTING:**
TOILET REQUIREMENT: **GIRLS:** NIL **BOYS:** YES
IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1PH + 1nos girls.	1nos Boys to be repaired
2	URINALS		1) Girls to be repaired 2) Boys to be constructed
3	DOORS(SIZE)	✓	
4	FLOOR LEVEL	X	Girls Urinal & Boys toilet to be repaired.
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER	X	to be constructed
9	LEASE PIT/ SEPTIC TANK	✓	Not functioning.

SOURCE OF WATER: **BORE WELL WITH PUMP:** **HAND PUMP:** YES
WATER TANK: **GROUND:** NIL **OVERHEAD:** ~~Nil~~ YES

WATER TANK CAPACITY:

Remarks if any:

- Water source required as hand pump not working
- Over head tank to be constructed as no source of water withing 1 km.
- Boys Urinal to be constructed

Sign of School Head Master
 Headmaster
 Upper Bausabati Project Pry. School
 NAME: Bhapur, Nayagarh
 Arjit Kumar Sahu

Prakash Kumar Panda
 Sign of School Mgt Committee
 Chairman S.M.C.
 Upper Bausabati Project Pry School
 NAME: Bhapur, Nayagarh

Sign of Surveyor
 NAME: Varun Kumar

Prakash Kumar Panda
 S.S. Pattanayak