

Name of head master - NARAYAN SAHU

Mobil No - 9178622876



District **BAHARI** Block **BHAWANI PATNA** Village **KARLASODA**
 School Name **RANBHATA P.S.** School Code **21260100902**

No. of Student **45** Girls- **21** Boys- **24**

Status of toilet Existing **NIL** Not Existing **YES**

Toilet Requirement Girls - **1** Boys - **1**

If Existing:

Sl.No	Item	Condition	
		Good In Nos.	To be replaced in Nos.
1	WC		1
2	Urinals		2
3	Doors (size)		2.00 x 0.6 = 1m - Road Condition
4	Floor level		X
5	Wall level		X
6	Internal plaster		X
7	Outer plaster		✓
8	Inspection Chamber		X
9	Lease pit / septic tank		X

Source of Water **HANDPUMP** Bore well with pump ^{NIL} / Hand pump - **1**

Water tank **X** Ground **X** / Overhead **X**

Water tank Capacity **X** *NO. space for new toilet as the land is in dispute.*

Remarks if any: *There is no school land, its running on private land which is in dispute and civil case is pending since last 20yrs.*

Narayan Sahu
 Sign of School Headmaster
 ନାରାୟଣ ପ୍ରସାଦ ସାହୁ
 ନାରାୟଣପୁରୀ-୨, ବାଲିଆପାଲି
 Name **NARAYAN SAHU**

Sign of School Mgt Committee
Trinath Bachha
 Name **TRINATH BACHHA**

Sign of Surveyor
Vinay Kumar
 12/2/2015
 Name **VINAY KUMAR**