

Name of head master - **TEBHASAHU**

Mobil No - 7894233989



District **KALAHANDI** Block **BHAWANIPATNA** Village **SIKUAN**

School Name **SIKUAN P.S**

School Code **21260107901**

No. of Student **41**

Girls **22**

Boys **19**

Status of toilet

Existing **1 No. Common**

Not Existing

Toilet Requirement

Girls

W/C - 1
U - 2

Boys

If Existing:

↓ 1 no.

↓ X

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	NIL	1
2	Urinals	2	2
3	Doors (size)		1 X 9.0 X 0.60 m
4	Floor level		✓
5	Wall level		✓
6	Internal plaster		✓
7	Outer plaster		✓
8	Inspection Chamber		✓
9	Lease pit / septic tank		✓

Source of Water **HANDPUMP**

Bore well with pump **X**

Hand pump **- 1 (one)**

Water tank **X**

Ground **X**

Overhead **X**

Water tank Capacity **X**

Remarks if any:

Space limited. 1 no. Girls toilet needed

Tebha Sahu

Sign of School head master

HEADMASTER

Sikuan Prymary School

Sadar-II, Kalahandi

Name **TEBHA SAHU**

ସରସ୍ୱତୀ ଘୋଷ

Sign of School Mgt Committee

CHAIR PERSON

S.M.C. Sikuan Prymary School

Sadar-II Kalahandi

Name **SARASWATI BHOI**

Sign of Surveyor

13/2/15

Name

R.R. Sahu