

Name - P/Head master - SUKRUJANI

Mobil No - 955660966



District KALAHANDI Block BHAWANIPATNA Village CHHELIMAL

School Name SUNDHIMUNDA P.S. School Code 21260103602

No. of Student 42 Girls- 20 Boys- 22

Status of toilet Existing 2 S.S.A under 2-13-Comk Not Existing

Toilet Requirement Girls 1 Boys 1

If Existing: 1

Sl.No	Item	Condition	
		Good In Nos.	To be replaced in Nos.
1	WC	/	1
2	Urinals	0	0
3	Doors (size)	0	0
4	Floor level	0	0
5	Wall level	0	0
6	Internal plaster	0	0
7	Outer plaster	0	0
8	Inspection Chamber	0	0
9	Lease pit / septic tank	0	0

Source of Water Hand pump Bore well with pump / Hand pump - 1 (one)

Water tank 0 Ground 0 / Overhead X

ONLY 57 STUDENTS

Remarks if any: - Old toilet is totally changed. Toilet Under S.S.A. (B-1, 2-1) under construction. Urgent need of toilet work stopped.

Sukru Jani Headmaster Sundhimunda P.S. School Name SUKRUJANI

Dole Swarajani Sign of School Mgt Committee

Sign of Supervisor 14/11/15 Name R.R. SINGH