

District Sambalpur Block Burla NAC Village ward No. 8  
~~Dhankuta~~ ~~Sadeipali~~  
 School Name Sadeipali P.S School Code 21031000704  
 No. of Student 85 Girls- 44 Boys- 41  
 Status of toilet Existing 2 existing Not Existing  
 and 1 under construction  
 Toilet Requirement Girls NO Boys -  
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>TWO</u>	
2	Urinals	<u>NIL</u>	
3	Doors (size)	<u>✓</u>	
4	Floor level	<u>✓</u>	
5	Wall level	<u>✓</u>	
6	Internal plaster	<u>✓</u>	
7	Outer plaster	<u>✓</u>	
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump  
 Water tank Ground / Overhead  
 Water tank Capacity

Remarks if any:  
one toilet is under construction since last 1 year. That toilet can be constructed by the company. Only wall and floor have been constructed. But other things need to be made

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

9/10/15  
 Head Master,  
 Sadeipali U. P. School  
 Burla

Name

Name

[Signature]  
 Chairman  
 Sadeipali P.S. School  
 BURLA

[Signature]  
 9.1.2015  
 1/KM. 9938549401.