

District Kangra Block Chakrabarti Village Archangi  
 School Name Archangi P.U.P.S School Code 21210203001  
 No. of Student 48 Girls- 26 Boys- 22  
 Status of toilet Existing 9 Not Existing  
 Toilet Requirement Girls PHC Boys 1  
 If Existing: 21

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>2</u>	
2	Urinals		
3	Doors (size)	<u>20 x 100 x 2.10</u>	
4	Floor level	<u>6.5000</u>	
5	Wall level	<u>2.5000</u>	
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber	<u>Need Repair</u>	
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump   
 Water tank Ground / Overhead  
 Water tank Capacity

Remarks if any: Boys Toilet is required.

Mutyunjaya Mallik प्रबन्धक  
 Sign of School head master Sign of School Mgt Committee  
**Headmaster**  
Mutyunjaya Mallik Chairman  
 Name Name  
2437397440  
 Sign of Surveyor Deenak