

District *Kandhamal* Block *Chakrapada*

Village *Gasamaha*

School Name *Gasamaha P.S.*

School Code *21210206201*

No. of Student *8* Girls- *4*

Boys- *4*

Status of toilet Existing

Not Existing *School Building*

Toilet Requirement Girls *Nil*

Boys *Nil under construction*

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<i>—</i>	
2	Urinals	<i>—</i>	
3	Doors (size)	<i>—</i>	
4	Floor level	<i>—</i>	
5	Wall level	<i>—</i>	
6	Internal plaster	<i>—</i>	
7	Outer plaster	<i>—</i>	
8	Inspection Chamber	<i>—</i>	
9	Lease pit / septic tank	<i>—</i>	

Source of Water

Bore well with pump / Hand pump *— 01*

Water tank

Ground / Overhead

Water tank Capacity

Remarks if any:

*School building is under constn.  
No toilet is required  
at present.*

*Hadubandhu Sahoo*

**Headmaster**

*Gasamaha Primary School*  
Sign of School Headmaster

Sign of School Mgt Committee

Sign of Surveyor

*8783160599*

Name *Hadubandhu Sahoo*

Name

Name

*19/02*