

District **KANDAMAL** Block **Charopeel** Village **Salaguda**
 School Name **Salaguda pups** School Code **21210202701.**
 No. of Student **100** Girls- **42** Boys- **58**
 Status of toilet Existing **NIL** Not Existing
 Toilet Requirement Girls **01** Boys **01.**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump **open well**
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: **Recommended for no boys and girls toilet** **16/08/20**

Ranjeet Kumar Sahu
 Sign of School head master
Ranjeet Kumar Sahu
 Name **8763181279**
 Project **Primary school**
SALAGUDA

Sign of School Mgt Committee
Deborah Mallick
 School Management Committee
 Name **P.U.P.S. Salaguda**

Sign of Surveyor