

District Kandhamal Block Chakrapal Village Rajkhol-e  
 School Name \_\_\_\_\_ School Code 21210201001  
 No. of Student 13 Girls- 07 Boys- 6  
 Status of toilet Existing 01 Not Existing \_\_\_\_\_  
 Toilet Requirement Girls 01 Boys 0  
 If Existing: \_\_\_\_\_

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		<u>01</u>
2	Urinals		<u>02</u>
3	Doors (size)		<u>3 x 0.75 x 1.80</u>
4	Floor level	<u>0.26</u>	
5	Wall level	<u>2.06</u>	
6	Internal plaster		
7	Outer plaster		<u>Need Repairing</u>
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump /  Hand pump  
 Water tank X Ground X / Overhead  
 Water tank Capacity \_\_\_\_\_

Remarks if any:

Recommend for no more Girls Toilet

S.K.  
 Headmaster  
 Primary School  
 Tatakimendi Kandhamal  
 Sign of School head master

S. Machola  
 Sign of School Mgt Committee

Sign of Surveyor

Santash KUDAS  
 Name

Chairman  
S.M.C. Tatakimendi P.S.  
 Name S. Machola

Name

D. Sar