

District: - Rayagada

Block: - CHANDRAPUR

Village: - BELENDI

School Name: - BELENDI N.P.S

School Code:-

No. of Student: - 31

Girls: - 17

Boys: - 14

Status of toilet: -

Existing: - ① Under const. upto roof Not existing:-

Toilet Requirement: -

Girls: - ② Under const. upto plinth. Boys:-

If Existing:-

Sl no.	Item	Condition	
		① 3.55 X 2.10 X 3.10	② 4.55 X 2.40 X 0.60
		Good in Nos.	To be replaced in Nos.
1	WC	NA.	NA.
2	Urinals	NA.	NA.
3	Doors(Size)	Steel door - Good 2 No - 0.60 X 2.05	NA.
4	Floor level	Tiles - Good	NA.
5	Wall level	B. wall - Good	B. wall NA - upto plinth.
6	Internal Plaster	Good	NA.
7	Outer plaster	Good	NA.
8	Inspection Chamber	NA.	NA.
9	Lease Pit/Septic tank	NA.	NA.

Source of Water

Bore well with pump NA. /

Hand pump NA.

Water tank

Ground NA. /

Overhead NA.

Water tank Capacity

Remarks if any: ① The toilet is under construction. Roof slab done.
② The toilet is under construction up to plinth level.

Telottama Gauda
Headmaster
Primary School, Belendi
Chandrapur, Dist. Rayagada

S.M.C. Chairperson
Primary School, Belendi
Chandrapur Dist. Rayagada

Subash Chandra Namde
Sign of Surveyor

Name Telottama Gauda

Name Kriti Brekbeda

Name Subash Chandra Namde

Email ID:

Email ID

Email ID subashnamde@gmail.com

Ph.No. 06863 242001

Ph.No.

Ph.No. 943 8878808