


152

District **Tajpur** Block **Danagadi** Village **Barigodha**
 School Name **Barogodha P.S.** School Code **21130408302**
 No. of Student **41** Girls- **26** Boys- **15**
 status of toilet Existing **1 (Bd G)** Non-Existing
 Toilet Requirement Girls **1 (Totally damaged)** Boys
 If Existing:

Sl.No	Item	Condition	
		(B+G) Good in Nos.	(B+G) Replaced in Nos.
1	WC	1	
2	Urinals.	Nil	
3	Doors (size)	2x0.74x1.94	
4	Floor level	0.25	Totally damaged
5	Wall level	2.23	Totally damaged
6	Internal plaster	Good	
7	Outer plaster	Good.	
8	Inspection Chamber	X	
9	Lease pit / septic tank	X	

Source of Water **hand pump** Bore well with pump Hand pump
 Water tank Ground Overhead
 Water tank Capacity

Remarks if any: **No Toilet is required as there is one good existing toilet for Boys and girls.**


 Sign of School head master

Sign of School Mgt Committee

M. Sahoo
 21/02/15
 Sign of Surveyor

Barigodha Prv. School
 Name **Laxmikanta Jena.**
9437742358

Name

Name **Manoranjan Sahoo**



Ch Mohan Kish