

155

District **Tajpur** Block **Danagadi** Village **Dasmaina**  
 School Name **Dasmaina p.s** School Code **21130404801**  
 No. of Student **118** Girls- **53** Boys- **65**  
 status of toilet **Existing** **1** **(Totally Damaged)** **Note: Existing**  
 Toilet Requirement Girls **0** Boys **0**  
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	/	/
2	Urinals.		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water **hand pump** Bore well with pump / Hand pump /  
 Water tank Ground / Overhead  
 Water tank Capacity

Remarks if any: **Both boys and Girls toilet is required**

**Sandhyaarani Mahanty**  
 Sign of School head master  
**Headmaster**  
**Dasmania Pry. School**

Sign of School Mgt Committee

**M. Sahoo**  
 14/7/15  
 Sign of Surveyor

Name **Sandhyaarani Mahanty** Name  
**9338457917**

Name **Menoranjan Sahoo**

**M. Sahoo**  
 14/7/15

**A. Mohan Kumar**