

163

District **Jajpur** Block **Danagadi** Village **Managobindapur.**
 School Name **Managobindapur Nodal UPS** School Code **21130402003**
 No. of Student **380** Girls- **165** Boys- **215**
 status of toilet **Existing 1 (Boys/Girls) Not Existing**
 Toilet Requirement Girls **0** (No Toilet Totally damaged) Boys **0**
 If Existing:


Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1
2	Urinals.	1	1
3	Doors (size)		3 x 0.58 x 1.52
4	Floor level	0.25	
5	Wall level	1.27	
6	Internal plaster	good	
7	Outer plaster	good	
8	Inspection Chamber		1 (damaged)
9	Lease pit / septic tank	X	

Source of Water **hand pump** Bore well with pump / Hand pump **0**
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: **Since strength of the students is high, Two Toilets (one boys & one girls) is required.**


 Sign of School head master
Headmaster.

Sign of School Mgt Committee


 Sign of Surveyor

Managobindapur Nodal U.P School

Name

Name

Name **Manoranjan School**

Bhagirathi Pradhan
9668272279



Ch. Mohan Kishor