

165

District **Tajpur** Block **Danagadi** Village **Manapur**  
 School Name **Manapur High School** School Code **21130402803**  
 No. of Student **270** Girls- **143** Boys- **127**  
 status of toilet **Existing (B) 1 + 1 (B&G)** Note: **Existing**  
 Toilet Requirement **Girls** Boys  
 If Existing:

Sl.No	Item	Condition			
		(B) Good	In Nos (B&G)	To be replaced (B)	To be replaced (B&G)
1	WC	Nil	3		3
2	Urinals	4	Nil	4	
3	Doors (size)	X		X	3x0.68x1.53 3x0.62x1.82
4	Floor level	X	0.40.	X	
5	Wall level		1.90.	1.67, 1.15	
6	Internal plaster	Good.	3 (Good)		3 (damaged)
7	Outer plaster	Good.	6 (Good)		
8	Inspection Chamber	X	2 (Good)	X	
9	Lease pit / septic tank	X	2 (Good)	X	

Source of Water **Dog well (comes under hostel)** Bore well with pump **X** / Hand pump **1 (Not working)**.  
 Water tank **Nil** Ground **X** / Overhead **X**  
 Water tank Capacity **X**

Remarks if any: **1 No girls Toilet is required.**

*[Signature]*  
 Sign of School head master  
**Headmaster**

*[Signature]*  
 Sign of School Mgt Committee

*[Signature]*  
 Sign of Surveyor

**Manapur High School**  
 Name **Pravati Mishra** Name  
**Manapur High school**  
 Mob- **8908535381**

Name **Manoranjan Sahoo**  
*[Signature]*

*[Signature]*