

169

District **Tajpur** Block **Danagadi** Village **Nilamanideipur.**  
 School Name **Binapani Bidyapitha** School Code **21130407301**  
 No. of Student **123** Girls- **71** Boys- **52**  
 status of toilet **Existing (1+)** Note- **Existing**  
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition			
		(Boys) Good in Nos.	(Girls)	(Boys) Replaced in	(Girls)
1	WC	2+1	1		
2	Urinals.	2+2	1+3		1
3	Doors (size)	1x0.70x1.95	1x0.70x1.95	2x0.60x1.79	1x0.60x1.50
4	Floor level	0.10	0.10.	0.10.	0.10
5	Wall level	2.27	2.27.	2.10	1.60
6	Internal plaster	2(good.)	good.		
7	Outer plaster	good.	good	damage.	
8	Inspection Chamber	1(good)			
9	Lease pit / septic tank	X	1(good)		

Source of Water **hand pump** Bore well with pump / Hand pump /  
 Water tank **1** Ground / Overhead  
 Water tank Capacity **750 lt.**

Remarks if any: **No extra toilet required.**

Sign of School Headmaster  
**Binapani Bidyapitha**  
**Nilamanideipur**

Name **Bhanashyam Moharaj**  
**9438140615**

Sign of School Mgt Committee

Sign of Surveyor  
**M. Sahoo**  
**19/02/15**

Name **Manoranjan Sahoo**

**Ch. Mohan Kish**

**Ch. Mohan Kish**