

179

District **Tajpur** Block **Danagadi** Village **Tungeisoni**
 School Name **Tungeisoni NPS** School Code **21130404101**
 No. of Student **95** Girls- **45** Boys- **50**
 status of toilet **Existing 1 (boys)** **Not Existing**
 Toilet Requirement **Girls** **Boys**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1
2	Urinals.		1
3	Doors (size)	2 x 0.60 x 1.83	
4	Floor level	0.45	0.45
5	Wall level		2.10
6	Internal plaster		damaged
7	Outer plaster		damaged
8	Inspection Chamber		1 (damaged)
9	Lease pit / septic tank		X

Source of Water **hand pump** Bore well with pump / Hand pump **1**
 Water tank **X** Ground / Overhead
 Water tank Capacity **X**

Remarks if any: **1 No. Girls toilet is required.**

S. Kumar
 20/21/2019
 Sign of School head master

Sign of School Mgt Committee

M. Sahoo
 20/02/19
 Sign of Surveyor

Soni Kumar
 Name **Behera**
9437291465
Headmaster
Tungeisoni Primary School

Name **Manoranjan Sahoo**
M. S. Sahoo
20/02/19
Ch. Mohan Kumar