

183

District: **Tajpur** Block: **Daseralkipur** Village: **Bajaspata**
 School Name: **Nalmallickpatana Project UPS** School Code: **21130511302**
 No. of Student: **202** Girls: **103** Boys: **99**
 Status of Toilets: **Existing 1 (damaged)** Existing
 Toilet Requirement: **Girls 1** Boys: **1**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1
2	Urinals		X
3	Doors (size)		X
4	Floor level		6-10
5	Wall level	1-8	↔
6	Internal plaster	damaged	
7	Outer plaster	damaged	
8	Inspection Chamber	X	
9	Lease pit / septic tank	>	

Source of Water: **Hand pump** Bore well with pump: Hand pump: No
 Water tank: Ground: Overhead:
 Water tank Capacity:

Remarks if any: **As the connections are more, 100' more large tank is required -**

S. Maunick
 Sign of School head master

Sign of School Mgt Committee

S. Behera
 13/2/15
 Sign of Surveyor

Nalmallickpatana Project U.P. School
Nalmallickpatana
 Name

Name

Name **S. Behera**

Snehalata Maunick
9853310155

Manoranjan Sahas

Manoranjan Sahas