

194

District **Jaipur** Block **Dasarathpur** Village **Dudhara 7a.**
 School Name **Garibabandhu H.S.** School Code **2130505603**
 No. of Student **110** Girls- **45** Envs- **65**
 status of toilet **Existing (girls)** ~~Not Existing~~
 Toilet Requirement Girls **1** Boys **1**
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1	
2	Urinals		4
3	Doors (size)	2 x 0.6 x 1.70 1 x 0.6 x 1.70	
4	Floor level	0.30	
5	Wall level	1.52, 1.90	
6	Internal plaster	good	
7	Outer plaster	good	
8	Inspection Chamber	✓	
9	Lease pit / septic tank	X	

Source of Water Bore well with pump / Hand pump **1 (Not working)**
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: **As the students are more, 1 no girls toilet is required.**

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

Jaganendra Kanth
 Name **G/C H/S**

Name

S. Bahere
 Name

Headmaster
Garibabandhu High School

(Signature)

Manoranjan School