

196

District Dajpur Block Dasatalkpur Village \_\_\_\_\_  
 School Name Daulabada P.S. School Code 21130513701  
 No. of Student 22 Girls 10 Boys 12  
 Status of toilet Existing 1 (girls) Not Existing  
 Toilet Requirement Girls \_\_\_\_\_ Boys 1

If Existing:

Sl. No.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1
2	Urinals		6
3	Doors (size)		1x1.00x1.70
4	Floor level	0-10	
5	Wall level	1.50, 2.00	
6	Internal plaster	good	
7	Outer plaster	good	
8	Inspection Chamber	X	
9	Lease pit / septic tank	1	

Source of Water Hand pump Bore well with pump / Hand pump 1  
 Water tank \_\_\_\_\_ Ground / Overhead \_\_\_\_\_  
 Water tank Capacity \_\_\_\_\_

Remarks if any: 1 No. boys toilet is required.

[Signature]  
 Sign of School head master  
Prasad Kumar Panigrahi  
 Headmaster  
 Deulbad P.S. School

[Signature]  
 Sign of School Mgt Committee  
 Sign of Surveyor  
 Name G. Behera

9439968032

[Signature]

Mangarajan Sahoo