

DL. 23.07.2015 (14)

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: Dasapalla

VILLAGE: Hanumantha

SCHOOL NAME: Hanumantha PUPS

SCHOOL CODE: 0203401

NO. OF STUDENT: 118 GIRLS: 60

BOYS: 58

STATUS OF TOILET: EXISTING: YES

NOT EXISTING:

TOILET REQUIREMENT: GIRLS: ~~10~~

BOYS:

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 nos	1 nos
2	URINALS	2 nos	2 nos both boys & girls.
3	DOORS(SIZE)	X	3'x6' - 4 nos.
4	FLOOR LEVEL	X	Require Repair
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	X	Repair required.
7	OUTER PLASTER	✓	Maintenance required
8	INSPECTION CHAMBER	X	New Construction required
9	LEASE PIT/ SEPTIC TANK	X	do

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP: YES

WATER TANK:

GROUND: YES

OVERHEAD:

WATER TANK CAPACITY: 450 lt

Remarks If any:

1. Over head required & Ground tank has no supply connection & water stored in the tank by through bucket by the students.

Barck
23/07/15
Sign of School Head Master
Govt. U.S.H.S. Hanumantha
Dasapalla Dist. Nayagarh
NAME: Antashwari Barck

Sign of School Mgt Committee
Hanumantha PUPS
Dasapalla, Nayagarh
NAME: Arjuna Naik

Sign of Surveyor

NAME: S.S. Pattanayak

Vann
Vann Kumar