

District Mandhwal Block Tikabali Village Raibhanja
 School Name _____ School Code 212/1112901
 No. of Student 12 Girls- 7 Boys- 5
 Status of toilet Existing Damaged & Dysfunctional Not Existing
 Toilet Requirement Girls 01 Boys _____
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any:
 i) 01 toilet block for girls is required.
 ii) Water from Handpump is not potable.
[Signature]
 16/02/15

Jayram Pradhan
 Sign of School head master
Headmaster
Primary School, Raibhanja,
Dist- Mandhwal.
 Name _____
 Mob- 9437433106

Sign of School Mgt Committee
 Name _____

Sign of Surveyor [Signature]
Sanoj Kumar
 Name _____