

Kandhamal.

District _____ Block G. Udayagiri Village Grossingia
School Name Grossingia U.P.S. School Code 2120400701
No. of Student 261 Girls- 97 Boys- 164
Status of toilet Existing toilets are damaged (Non functional) Not Existing _____
Toilet Requirement Girls 2 Block Boys 2 Block

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump

Water tank Ground / Overhead

Water tank Capacity _____

Remarks if any:

Water supply connection will be made available within short period from Govt R.W.S.S.

Bibhuti Acharya.

Signature of School head master

U.P. School
Grossingia

Signature of School Mgt Committee

Signature of Surveyor

Name Mr. Bibhuti Acharya
943706668A

Name