

District *Kandhamal* Block *G. Udayagiri* Village *Raikala*
 School Name *Raikala UPS* School Code *21210405702*
 No. of Student *64* Girls- *29* Boys- *35*
 Status of toilet Existing *9=2* Not Existing
 Toilet Requirement Girls *Nil* Boys *Nil*

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<i>2+2</i>	
2	Urinals	<i>✓</i>	
3	Doors (size)	<i>✓</i>	
4	Floor level	<i>✓</i>	
5	Wall level	<i>✓</i>	
6	Internal plaster	<i>✓</i>	
7	Outer plaster	<i>✓</i>	
8	Inspection Chamber	<i>✓</i>	
9	Lease pit / septic tank	<i>✓</i>	

Source of Water Bore well with pump / Hand pump *-ol. Remog*

Water tank Ground / Overhead

Water tank Capacity

Remarks if any:

*No water supply system requirement.
 No toilet is required.*

for - heery
 Sign of School head master
 Headmaster
 U.P. School, Raikala
 G. Udayagiri (Kandhamal)

Sign of School Mgt Committee

Sign of Surveyor

Name *LOkanatha Barik*
9438029068

Name

Name