

03
27-01-15

District Dhenkanal Block Gondig Village Neulapoi/Chandrasekharpur
 School Name Chandrasekhar H.S School Code 21140313601
 No. of Student Girls- 76 Boys- 88
 Status of toilet Existing Not Existing
 Toilet Requirement Girls - 01 Boys - 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>01</u>	<u>01</u>
2	Urinals	<u>NIL</u>	
3	Doors (size)	<u>Toilet 0.57x1.83</u> <u>U.R. 0.70x1.35</u>	
4	<u>wall</u> Floor level	<u>Toilet - 1.85</u> <u>Urinal - 1.35</u>	
5	<u>Floor</u> Well level	<u>+0.25</u>	
6	Internal plaster	<u>Good</u>	
7	Outer plaster	<u>Good</u>	
8	Inspection Chamber	<u>NIL</u>	
9	Lease pit / septic tank	<u>2 Nos lead pit</u>	

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
Defunct open well May - June dry during Apr - June.

Water tank Capacity $\pi \times (1.5)^2 \times 1.2$ (Ground)
 $\pi \times (1.2)^2 \times 1.2$ (OH)
 At toilet - $0.74 \times 0.85 \times 0.97$ (Ground)

Remarks if any: Urinals are open to sky and urinate on floor which is unhygienic. Considering the strength additional toilet for both boys and girls is required.

Panda
 Sign of School Head master
Headmaster

Sign of School Mgt Committee

[Signature]
 27-01-15
 Sign of Surveyor

Chandrasekhar High School

S.R. Mishra
 9438879727
 Name

U/Po- Neulapoi, Dist- Dhenkanal Name

Saikatanta Kumar Panda

9437904757

[Signature]
 27/1/15