

39

"स्वच्छ भारत अभियान"

DISTRICT: Gajapati

BLOCK: Gumma

VILLAGE: Gumma

SCHOOL NAME: Gumma P.S.

SCHOOL CODE: 21200207203

NO. OF STUDENT: 250

GIRLS: 147

BOYS: 103

STATUS OF TOILET: 02

EXISTING: 02

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 02

BOYS: 02

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		Fully damaged
3	DOORS(SIZE)		Fully damaged
4	FLOOR LEVEL		required
5	WALL LEVEL		Not usable
6	INTERNAL PLASTER		condition
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: N.A.

BORE WELL WITH PUMP: Y

HAND PUMP: X

WATER TANK: N.A.

GROUND:

OVERHEAD:

WATER TANK CAPACITY:

Remarks if any: Renovation reqd for existing toilets and addition of 04 toilets are reqd.

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor 25/01/14

NAME: Jyoti Prasad Singh

NAME: Sourabh Singh

NAME: Leshu