

GIRLS

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING
BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada Block: - GUNUPUR Village: - DAMBASORA
 School Name: - DAMBASORA P. S. School Code: - 21270405301
 No. of Student: - 122 Girls: - 67 Boys: - 55
 Status of toilet: - Existing: - YES (1 no.) Not existing: -
 Toilet Requirement: - Girls: - Girls & Boys Boys: -
 If Existing: -

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	YES (01 no.)	
2	Urinals	Yes	
3	Doors(Size)	0.85 X 1.80 mt 0.80 X 1.80 mt	
4	Floor level	Tile	
5	Wall level	Brick work	
6	Internal Plaster	Yes	
7	Outer plaster	Yes	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	Yes	

Source of Water Bore well with pump NA / Hand pump 01 no.

Water tank NA Ground NA / Overhead NA

Water tank Capacity

Remarks if any:

Panda
HEAD MASTER
 Primary School, Dombosora
 Sign of School Head Master

ସାଉଦାମିନି ସାହୁ
Chairperson S.M.
 Primary School,
 Dombosora Dt Rayagada
 Sign of School Mgt Committee

Pradhan
 Sign of Surveyor

Name *Allhadini Panda*

Name *Saudamini Sahukar*

Pradhan
 Name *Pradhan*

Email ID

Email ID

Email ID

Ph.No. 9556971990

Ph.No.

Ph.No. 9938631916